

IMPORTANT PACKAGING REMOVAL INSTRUCTIONS

Remove the hard transit packaging from the table-top carton before beginning assembly.

Packaging removal time  2 People	Estimated time  15 minutes	Tools Needed (Not Included)  Phillips screwdriver
--	--	---




KEEP THE CARTON FLAT.

Do not lift the table top until all wooden and metal transit supports have been removed.


Step 1 - Remove the wooden transit beams

Using a Phillips screwdriver, remove the two screws at each end of every wooden beam (four screws per beam). Lift all five beams away from the carton.



Step 2 - Remove the metal transit bars

Lift away the loose cardboard or plywood protection. The fixing screws are in the cream-coloured side rails at both ends of each metal bar: remove two screws at each end (four screws per bar), then lift both bars out.



After both stages are complete:

Continue with the separate assembly instruction leaflet supplied in the carton.

Stock Code:H5212/18-3

Batch: POR177007

Page 1 of 1